




INSTALLATION GUIDE

THE "BALANCED PIPE LOOP" IS THE PREFERRED PIPING METHOD WHEN INSTALLING MULTIPLE JETS. IF THIS IS NOT FEASIBLE, EXTEND THE 2" SUPPLY LINE AT LEAST 5' PAST FURTHEST NOZZLE(S) BEFORE TERMINATING/CAPPING LINE(S).



NOTE: IF PRECISE STREAM BALANCING IS CRITICAL, THEN INSTALL A VALVE ON EACH LINE FEEDING EACH NOZZLE, A MINIMUM OF 12" BACK FROM NOZZLE INLET CONNECTION.